## भारत सरकार (GOVERNMENT OF INDIA) रेल मंत्रालय (MINISTRY OF RAILWAYS) रेलवे बोर्ड (RAILWAY BOARD)

No. 2023/CE-II/Safety/Instruction

New Delhi, dated 03.01.2025

Principal Chief Engineer, All Zonal Railways.

Sub: Precautions to be observed while working in LWR/CWR territory.

1. An unusual incidence of buckling has occurred in one of railways in the month of Dec-24. At the site of incidence, the gangmate had opened 16 numbers of continuous sleepers to replace the crushed rubber pads, thereby violating the provisions of Para 345 of IRPWM-2024. The relevant extracts are reproduced below:

## 345(1)(a):

The regular track maintenance in LWR/CWR shall be confined to hours when the rail temperature is between  $td+10^{\circ}C$  and  $td-30^{\circ}C$  and shall be completed well before onset of summer. However, for LWR on wider base sleepers, regular track maintenance shall be confined to hours when the rail temperature is between  $t_d+15^{\circ}C$  and  $t_d-30^{\circ}C$ .

## <u>345(5)</u>:

**Renewal of fastenings** – The work of renewal of fastenings shall be carried out when rail temperature is within the limits specified in Para 345 (1) (a) & (b) with following additional precautions:-

- (a) Renewal of fastenings not requiring lifting of rail Fastenings not requiring lifting of rails, shall be renewed on not more than one sleeper at a time. In case fastenings of more than one sleeper are required to be renewed at a time, then at least 15 sleepers in between shall be kept intact. Work shall be done under supervision of Keyman.
- (b) Renewal of fastenings requiring lifting of rail Fastenings requiring lifting of rails i.e., grooved rubber pads, etc. shall be renewed on not more than one sleeper at a time. In case fastenings of more than one sleeper are required to be renewed at a time, then at least 30 sleepers in between shall be kept intact. Work shall be done under supervision of Gang Mate.

Alternatively, if prevailing rail temperature is lower than td-10, fastening up to 5 sleepers on either side may be removed for replacement of rubber pad under the rail.

- 2. Time and again, it has been emphasized that maintenance of LWR/CWR needs to be carried out diligently as per provisions of IRPWM, duly considering the destressing temperature and prevailing rail temperature.
- 3. Railways are again requested to sternly instruct supervisors in the field to follow laid down instructions while working in LWR/CWR territory. Field staff also must be regularly trained and counseled regarding precautions to be observed during maintenance of LWR/CWR. Further, during field inspections, officers should also check the knowledge of P.Way officials regarding precautions to be taken while working in LWR/CWR territory and counsel them, if needed.

Director, Civil Engg. (Plg) Railway Board