भारत सरकार (GOVERNMENT OF INDIA) रेल मंत्रालय (MINISTRY OF RAILWAYS) रेलवे बोर्ड (RAILWAY BOARD)

No. 2015/CE-II/TK/14

New Delhi, Dated: 26.03.2025

Principal Chief Engineer, All Zonal Railways.

Sub: Safety precautions at Worksites.

A case of unusual incidence of hitting of locomotive of passenger train with a sleeper at worksite has been reported. Instructions have been issued from Board time to time to ensure safety at worksites to prevent any untoward incidents/accidents.

To ensure safety at worksites and prevent any reoccurrence of such incidents, following instructions are being reiterated:

- 1. Maintenance work on track to be done only after ensuring proper protection of track/ worksite as per laid down instructions. Wherever required, staff should be posted for look out duty.
- 2. Protection of worksites must be rechecked for correct locations of caution boards, flagmen etc.
- 3. Track maintenance or renewal activities for which block protection is required as per IRPWM, should be undertaken only under traffic block.
- 4. Proper training should be imparted regularly to the staff working on running track. All field staff should be sensitized by senior subordinates and officers about safety through counseling/seminars /workshops. Records of these safety awareness activities should be maintained.
- 5. Violations, if any, should be monitored and strict action should be taken against defaulters.

Zonal Railways are requested to follow the above in true spirit.

Saurabh Jain Dir. Civil Engg. (Plg.) Railway Board