

भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड Railway Board



No.2017/M(C)/138/2

(E-File no. 3325465)
Dated: 19.01.2022

PCMEs
All Zonal Railways

Sub: En-route detachment of coach No. WR-124997 GS of Train No. 22948 (Bhagalpur-Surat) Superfast Express.

There has been a case of en-route coach detachment, suspected due to breakage of lower spring beam of ICF GS coach No. WR 124997 in train no. 22498 (Bhagalpur-Surat) superfast express in WCR on 18.01.2022.


In this context, it is advised to properly examine all under gear components, fittings, its fasteners and welded joints during pit line examinations, En-route examinations, IOH/SS-I, POH/SS-II and other maintenance schedules.

A drive may immediately be launched to check under gear components in detail in all coaches undergoing pit line examination and available as spare and records of the drive should be updated over CMMS for each coach.

The detailed sequence for uploading data for the drive over CMMS is enclosed as **Annexure I**.

It is further advised to ensure coverage of entire fleet of Passenger coaches under this drive by 30th Jan 2022.

Strict compliance may please be ensured.


(सुमन कुमार तंती)
निदेशक / यांत्रिक इंजी. कोचिंग
रेलवे बोर्ड

C/- PED/CAMTECH for necessary information and action please.

ED/Carriage/RDSO for necessary information and action please.