



भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड Railway Board



No.2021/M(C)/143/1_Inspection -II

(E-File No. 3347618)
New Delhi dated: 11.09.2023

General Manager,
East Central Railway

Sub: Inspection of off-POH rake of ECR.

An off POH rake comprising of GS, WGSCN & GSLR coaches was inspected by MTRS and other officials from Board on 04.09.23 at NDLS station. The condition of these coaches was not found upto the mark and quality of POH needs to be substantially improved. Major deficiencies observed in these coaches are:

- Stensiling was done in place of Screen painting for coach no., signages etc.
- Bidding over panels were either not fitted/broken/not painted
- Painting was done without proper corrosion removal and surface preparation leading to dripping of paint.
- Lavatory doors were misaligned.
- Window frames were jammed and deteriorated.
- Interior panels were of different shades.
- Extra holes in the panels not properly plugged.
- Glass Windows not properly cleaned
- Electrical plug points and mobile charging points of varied designs/shapes
- Broken water bottle holders

These coaches were recently attended for major schedule (POH) in HRT workshop. The workshop should be suitably advised to improve the standards of POH especially wrt to aesthetics and passenger amenity items of Rolling Stocks.

For necessary action please

Copy

PCME

Copy

PCME

Copy to:

PCME/ECR - For information and necessary action please.

निदेशक

रवि जैन

(रवि जैन)

कार्य.निदेशक / यांत्रिक इंजी. को.
रेलवे बोर्ड