

7/17

rc

भारत सरकार **GOVERNMENT OF INDIA**
 रेल मंत्रालय **MINISTRY OF RAILWAYS**
 (रेलवे बोर्ड **RAILWAY BOARD**)

No.95/M(C)/141/1 Pt.

New Delhi, dated: 17.04.2018

Principal Chief Mechanical Engineers
All Zonal Railways


Sub: Rakes with Zero Missing Fittings.

Instructions regarding turning out Passenger rakes with Zero Missing fittings in coaches have be reiterated time and again. These are also included in the instructions regarding Maintenance Pattern of trains issued vide Board's letter No.95/M(C)/141/1 Pt. Dated 14.06.2017.

However, the public complaints received on this account and the rake inspection notes of officials indicate that these instructions are not being followed in letter and spirit by field units.


In this reference, it is desired that due emphasis may be given to turning out coaching trains with Zero Missing fittings. During interaction with Maintenance Staff and Supervisors, they should also be sensitized about provision of 100% passenger amenity item during Primary Maintenance of trains.

Please ensure compliance.


 17/4/2018

(Dimpy Garg)
Ex. Dir. Mech. Engg. (Chg.)
Railway Board

कृपया ध्यान दें
 20/4/18
 17/11



rc