

2021/M(C)/142/4 (6)

New Delhi, Dated - 22.04.22

The Principal Chief Mechanical Engineers,
All Zonal Railways.

Sub: Distribution of RSP work of Retrofitment of revised wiring with modified junction boxes and connectors for 5,000 coaches (P.B. Item No. 1270/22-23).

Ref: (i) Railway Board letter No. 2021/M(C)/142/4 (6) Dated 09.07.21.

(ii) Dir/Carriage/RDSO's letter No. No.MC/LHB/Brake Dated 27.02.19.

RSP work of Retro fitment of revised wiring with modified junction boxes and connectors for 5,000 coaches sanctioned under Pink Book Item No.713/22-23 (1314/21-22) was distributed among Zonal Railways vide letter under reference (i) above. However, there has been NIL progress against the work as indicated below:-

ZRs	Allotment	Execution	Balance still not executed	ZRs	Allotment	Execution	Balance still not executed
CR	100	0	100	SR	460	0	460
ER	489	0	489	SCR	40	0	40
ECR	557	0	557	SECR	326	0	326
NR	200	0	200	SWR	780	0	780
NER	600	0	600	WR	150	0	150
NFR	900	0	900	WCR	348	0	348
NWR	50	0	50				

Another RSP work of Retrofitment of revised wiring with modified junction boxes and connectors for 5,000 coaches has been sanctioned under P.B. Item No. 1270/22-23). Based on requirement received from ZRs, the subject RSP work is distributed among ZRs as per the following distribution:-

Zonal Railway	Distribution (coaches)	Zonal Railway	Distribution (coaches)
CR	700	NWR	400
ER	700	SR	400
ECR	100	SCR	500
ECOR	100	SER	500
NR	600	SECR	0
NCR	0	SWR	0
NER	700	WR	200
NFR	100	WCR	0
Total		5000	

Zonal Railways are advised to expedite the retrofitment work in LHB coaches as per RDSO instructions under reference (ii) above or latest and target completion of both the RSP works in 22-23.

Zonal Railways are advised to accordingly indicate fund requirement against the RSP work at appropriate budgetary stages (RE, FM).

(सुमन कुमार तौता)

निदेशक / यांत्रिक इंजी. को.

रेलवे बोर्ड

Copy to: ED/Carriage/RDSO – For kind information and necessary action please.