

No. 2011/M(C)/137/4Wheels

(E-File no. 3330107)
New Delhi, Dated 02.09.2022

PCMEs,
All Zonal Railways & KRCL

PCMEs
ICF, RCF and MCF

Sub: Wheel disc crack in LHB coach of Heat lot no. 2111130 M/s KLV make.
Ref: Railway Board letter no. 2011/M(C)/137/4Wheels dated 31.08.2022.


Recently IR has witnessed two cases of Wheel disc crack in LHB coaches. In this regard, vide letter under reference ICF, RCF, MCF and all coaching workshops including RCNK/SONIPAT and MLR workshop/JHs were advised to check the wheel pressing details since 01.04.2021 and accordingly advise the concerned Railways regarding fitment of wheel disc of Heat lot 211130 of KLV make under intimation to Board. It was also advised to check all Store depot/Shop floor for availability of any wheel disc of this heat lot.

In this regard, it is advised to furnish details in following format:

I. Details of Wheel pressed from 01 Apr 2021 to 31.08.2022				
Total No. M/s KLV make wheel disc pressed by Workshops/Units	Details of M/s KLV make wheel disc fitted heat lot wise			
	Heat Lot No.		Nos. of wheel disc	
II. Details of coaches/wheel set fitted with wheel disc of Heat Lot 211130 of M/s KLV (from 01.04.2021 to 31.08.2022)				
Wheel Disc No.	Wheel set No.	Coach No.	Depot	Zonal Railways
III. Details of wheel disc of Heat Lot 211130 of M/s KLV lying in Store depot/shop floor at present				
Location	Total Nos. of wheel discs		Wheel disc No.	

The above information may please be furnished by 17:00 Hrs, 02.09.2022 under signature of CWMs/CPLEs without fail.

The matter may please be treated as **Most urgent**.


(रवि जैन)

कार्य.निदेशक / यांत्रिक इंजी. को.

रेलवे बोर्ड

C/- CWMs/All Carriage workshops, CRSEs/All Zonal Railways for kind information and necessary action please.

-ED/Carriage/RDSO - for kind information and necessary action please.