

भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड Railway Board

E-Office - 3434262

New Delhi, Dated 09.08.2024

No. 2023/M(C)/141/6

General Managers
All Zonal Railways

Sub: Special Inspections to check water leakage in all AC Coaches.

A drive was launched from 07.07.2024 to 17.07.2024 to cover all AC Coaches for the areas concerned with water leakage/seepage. During thorough checking of these coaches, different issues have been observed across Zonal Railways.

The rainy season is still continuing over various regions. In this regard, Zonal Railways are advised to conduct similar 10 days drive to check all AC coaches covering all the aspects to ensure that no issue of water leakage etc. in AC coaches is observed during train operation.

Accordingly, necessary checks may be undertaken to check all the areas attended upon during initial drives/any other shortcoming found during this check. Some of the indicative items are mentioned below:

- Ensure cleaning of RMPU/Condensate drain holes.
- Ensure cleaning of End wall Drain Holes.
- To check RMPU Trough for intactness.
- Ensure the application of Sealant at all roof joints with coach body.
- Ensure the application of Sealant around RMPU bellows.

Detailed progress report to be updated daily on Board's Google sheet.

https://docs.google.com/spreadsheets/d/1tVwUJZoM0e3cQuV_JHWwt9i7gt_xdljCP-yylcQ8DjQ/edit?usp=drivesdk

20.08.24
09/08/24
(ऐश्वर्य सचान)

संयुक्त निदेशक / यांत्रिक इंजी. कोचिंग
रेलवे बोर्ड

C/- PCMEs/All Zonal Railways - for kind information and necessary action please.