

भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड Railway Board

(E-File no.3363200)

2021/M(C)/58/1/Mtg.&Conf.

New Delhi, Date: 24.10.2024

General Managers
All Zonal Railways,
ICF, RCF & MCF

Director General
RDSO, Lucknow

Sub. : Minutes of VC held on 23.10.2024 reg. Coaching & Freight Unusals

A VC was organized with PCMEs regarding issues in maintenance and unusals. The points noted during VC are as under:

SN	Item Discussed	Action by
1.	Vande Bharat Anti Roll Bar Fracture	
	a. ICF to review all drawings of VB bogie and update for Version 2 b. ICF to plan for supply of replacement for 120 coaches to Zonal Railways by December 2024. Action plan to be shared with Board. c. No rake should be turned out from ICF with old design of anti roll bar. d. Inspection Check sheet to be reviewed by ICF to include thickness of paint.	PCME /ICF PCME/ All Zonal Railways
2.	Derailment of EMU in Kalyan Shed	
	a. PCME/CR to thoroughly audit wheel section and process of measurement being followed in EMU/MEMU sheds and to take corrective action to avoid recurrence of similar failures.	PCME/CR
3.	Hot axle in 12452 Shram Shakti	
	e. Analysis of OMRS alerts, spring breakages, cases of wheel shelling, working of WSP, failures of suspension elements etc. should be investigated in detail by NCR and submitted again to Board.	PCME/NCR
4.	Fire in 11842 Gita Jayanti Exp	
	a. As per CAMTECH manual, Bearings of Alternator are to be replaced during alternate POH, which is not being done in GKP workshop. b. All CWEs to audit one section of workshops in their jurisdiction and to submit the report within a week. c. Audit of all sections of workshops to be carried by officer-in-charge on regular basis.	PCME/ All Zonal Railways
5.	Fire in Train 12445	
	a. Location of Aerosol based suppression system in SBC panel to be standardized by all PUs during manufacturing of coaches.	PED/RS/RDS O PED/PS&EM

	b. The provision of smoke detection point to be standardized in SBC panels of all coaches by RDSO. c. RDSO to undertake for testing of all contactors (critical location) by external agency. d. Plan for rectification/replacement of existing L&T make K-44 contactors to be submitted by 27/10/2024.	U/RDSO PCME/All PUs
6.	Fire in EMU	
	a. Proper locking and de-energisation of EMU/MEMU rakes to be ensured during night Stabling. All Railways to devise a plan jointly with the operating department. Action taken in this regard to be sent to Railway Board by 28/10/2024. b. Wherever EMU/MEMU rakes are stabled at points where C&W staff is not available, it is the responsibility of the station staff to ensure that proper locking is done. This should be ensured	PCMEs/ZR
7.	Hot axle in 22861 HWH KBJ Ispat express	
	a. Wheelset/CTRB should be replaced in case of Hot axle b. SER to implement the instructions for preventive wheel re-profiling.	PCME/SER
8&9	Freight Train Parting cases in ECR and DFCC	
	a. Uniform maintenance practices for CBC maintenance b. Implementation of CBC Committee report for must change items during ROH & POH	PCMEs/ZR

For necessary action please.


24/10/24

(प्रांजल मिश्रा)

संयुक्त निदेशक/ यांत्रिक इंजी. कोचिंग-II
रेलवे बोर्ड

Copy to:

1. PSO to MTRS: for kind information of MTRS.
2. PS to AM/ME: for kind information of AM/ME
3. PCMEs/All Zonal Railways, ICF, RCF & MCF – For kind information and necessary action please.
4. PED/RS/RDSO, PED/PS&EMU/RDSO - For kind information and necessary action please.