भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS (रेलवे बोर्ड RAILWAY BOARD)

No.99/M(C)/141/21

New Delhi, dt.28.10.2016

Chief Mechanical Engineers, All Indian Railways. RCF, Kapurthala, RCF, Rae Bareli and ICF, Chennai.

Managing Director, BEML, Bangaluru.

Sub: Provision of dustbin in Non-AC coaches under Mission 'Swachh Bharat Abhiyan'.

Ref: (i) Board's letters of even No. dated 20.11.2014 & 05.03.2015.

- (ii) CAI issued by ICF for provision of dustbins in Non-AC ICF coaches below outside washbasin dated 19.03.2015.
- (iii) CAI issued by RCF for provision of dustbins in Non-AC ICF coaches below outside washbasin dated 09.03.2015.
- (iv) CAI issued by RCF for provision of dustbins in Non-AC LHB coaches on the end wall dated 30.06.2015.

Vide Board's letters referred above, ICF, RCF/KXH, RCF/RBL and BEML were advised to provide suitable dustbins with pedal operated lid opening mechanism below the outside wash basin in all newly manufactured coaches. Further Carriage Alteration Instructions for retrofitment of dustbins in Non-AC coaches by the Zonal Railways in different types of coaches already in service have been issued by PUs and circulated to the Zonal Railways vide reference (ii), (iii) and (iv) above.

As the progress made in this direction is being reviewed in Board on a regular basis, Zonal Railways and PUS are requested to furnish the detail about the dustbins provided/retrofitted in the Non-AC coaches. The information may be sent by FAX (No.011-23388185) or by Email.

(Brijesh Dixit)

SOL

Director Mech. Engg. (Coaching)
Railway Board