

GF

भारत सरकार GOVERNMENT OF INDIA
रेल मंत्रालय MINISTRY OF RAILWAYS
(रेलवे बोर्ड RAILWAY BOARD)

No.99/M(C)/141/21/Pt.

New Delhi, dated:20.12.2017

PCMEs
All Zonal Railways
PCME/MCF, RCF, ICF

Sub: Leakage of water due to damage to health faucet

Cases of leakage of water in toilet due to damage to health faucet are getting reported to Railway Board. Since, presently, cut out cock for health faucet is not available, the leakage continues till attention is given at TXR point.

In this connection, it is desired that health faucets provided in coaches shall necessarily have provision of cut out cock to avoid problem of continuous enroute water leakage in case of malfunction / damage of health faucet.

All concerned may please be advised to ensure.


20-12

(Navaid Talib)
Dir. Mech. Engg. (Chg.)
Railway Board

C: ED/aw/RD50