

भारत सरकार GOVERNMENT OF INDIA  
रेल मंत्रालय MINISTRY OF RAILWAYS  
रेलवे बोर्ड (Railway Board)

No.2007/M(C)/141/1

New Delhi dated 21.07.2017

Chief Mechanical Engineers,  
All Zonal Railways.

Sub: POH of coaches.


-----

Lower Parel Workshop/Western Railway has set up a facility for overhauling of defective sealed window glasses during POH. The defective window glasses are opened, cleaned and resealed. This system set up by the Lower Parel Workshop is performing well and has helped in proper maintenance of defective sealed window glasses during POH.

2. The workshop has also set up facilities for buffing of all stainless steel items during POH. The quality of buffing during POH is very good and the buffed items have an appearance comparable to that of a new item.

3. Member Rolling Stock, during his inspection of the Workshop, has appreciated the two facilities set up by them. All other Zonal Railways should study these two systems adopted by Western Railway.

4. Board desires that action may be taken by the Zonal Railways to set up similar facilities in the POH workshops under their jurisdiction in order to improve the quality of work done during POH.



( डिम्पी गर्ग )

का.नि.यां.इं.(कोचिंग)

रेलवे बोर्ड