## भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS रेलवे बोर्ड (Railway Board)

No.2001/M(C)/137/10 Vol.II

New Delhi dated 19.07.2017

Chief Mechanical Engineer, ICF, RCF & MCF.

Sub: Removal of plastic films from newly manufactures coaches.

It has been observed that the new manufactured coaches turned out by the Production Units are at times having protective plastic films on the paneling and other items inside the coaches. Removal of these plastic films in the open line poses problems and becomes difficult to remove the complete film. Some portions of these films are left on the paneling material which gives a bad look to coach interiors. Further, at times, removal of these films causes scratches on the new paneling material. Photos of such an instance in which the films were not removed which attracted complaint are attached as annexure.

- 2. A serious view of such lapses has been taken by the Board. Production Units are directed to ensure 100% removal of the plastic material while turning out new manufactured coaches.
- 3. Chief Mechanical Engineers of Zonal Railways must also ensure that whenever new coaches are received without the complete removal of protective films, the coaches should be put in service only after the protective films have been fully removed. If required, assistance of the concerned PU where the coach has been manufactured may be taken.

Strict compliance of these instructions must be ensured.

( डिम्पी गर्ग )

का.नि.यां.इं.(कोचिंग)

रेलवे बोर्ड

Encl.: As above

Copy to: CMEs of All Indian Railways.





