भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS (रेलवे बोर्ड RAILWAY BOARD)

No.2009/M(C)/137/1 Vol-II

New Delhi, dated: 29.09.2017

Chief Mechanical Engineers All Indian Railways

Sub: Reporting of Coach Detachments.

It is often observed that coach detachments are reported by Zonal Railways after lapse of several hours. In this connection, instructions have already been issued for the immediate reporting of coach detachments to Railway Board.

This late reporting of coach detachments has been adversely commented upon by MRS. It is desired that the concerned CME shall immediately report all such incidents (preferably within one hour) to Board (MRS) with following particulars:-

1) Train No.

2) Primary / Secondary maintenance depot.

- 3) Place of incidence (with details of divisional zonal HQ).
- 4) Brief of incidence and cause of coach detachment.

Immediate compliance of above instructions may please be ensured.

(Navaid Talib) Dir. Mech. Engg. (Chg.)

Railway Board

9

-00 S.17