

GTF

भारत सरकार GOVERNMENT OF INDIA
रेल मंत्रालय MINISTRY OF RAILWAYS
(रेलवे बोर्ड RAILWAY BOARD)

No. 2019/M(C)/141/6_ (5048)

New Delhi, dated: 30.12.2020


PCMEs
All Zonal Railways

Sub: Derailment of Train No. 05048 Dn (Gorakhpur-Kolkata) Purvanchal festival special between Siho and Silout station of Sonpur Division on 20.10.2020.

In reference to the derailment of Train No. 05048 Dn (Gorakhpur-Kolkata) between Siho-Silout station on Barauni – Muzaffarpur section at Kms 73/03 of Sonpur Division on 20.10.2020, the SAG enquiry committee constituted for the enquiry of the case found that the cause of derailment is detachment of right side under slung water tank of the coach during its run.

In this regard, it is advised to properly examine all under gear components and fittings during primary maintenance and workshops should also be advised to ensure proper checking of fasteners and welding joints of under slung components especially water tank of coaches.

Strict Compliance to be ensured.


(Suman Kumar Tanti)
Dir. Mech. Engg./(Chg)
Railway Board

C/-PED/CAMTECH for necessary information and action please.
ED/Carriage/RDSO for necessary information and action please.