

09/11



भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड Railway Board



No. 2021/M(C)/141/2Pt2

(E-File no. 3377119)
New Delhi, Dated-27.04.2022

Director General,
RDSO, Lucknow

General Managers
ICF, RCF and MCF

Principal Chief Mechanical Engineers,
All Zonal Railways


**Sub: Malfunctioning of Bio-Vacuum toilets in Train No. 12441 BSP Rajdhani
dated 15.04.22.**

A case of malfunctioning of Bio vacuum Toilet has been noticed in train no.12441 on 15.04.2022. The bio-vacuum toilet malfunctioned and threw the waste upwards. Northern Railway has investigated the case in detail and has submitted report.

Further in this regard it is advised to take action as indicated below:

- i. All Zonal Railways are advised to launch a drive to check all the Bio vacuum Toilets simulating such situation of back flow and ensure that such incidences does not happen in future in any Bio Vacuum Toilets. Confirmation in writing from all the OEMs must accordingly be taken. The drive should be completed by 30 Apr 2022 and report accordingly should be sent to this office.
- ii. All Zonal railways/PUs and RDSO are advised assess the performances of all the vendors and take most stringent action against firms in view of this incidence and other incidences of serious concern.
- iii. RDSO is further advised to work out a solution by 30.04.2022 along with all the OEMs to detect such defects preemptively which may lead to back flow.

For immediate action please.


(सुमन कुमार तांती)
निदेशक / यांत्रिक इंजी./कोचिंग
रेलवे बोर्ड