



भारत सरकार Government of India  
रेल मंत्रालय Ministry of Railways  
रेलवे बोर्ड Railway Board



No.2021/M(C)/143/1\_Inspection - I

(E-File No. 3347618)  
New Delhi dated: 11.09.2023

General Manager,  
Western Railway

**Sub: Inspection of ICF rake of WR.**

An off POH rake comprising of GS, WGSCN & GSLRD coaches was inspected by MTRS and other officials from Board on 04.09.23 at NDLS station. The condition of these coaches was not found upto the mark and quality of POH needs to be improved substantially. Major deficiencies observed in these coaches are:

- Improper painting in washrooms and doorways.
- Rough welded patches near window sills.
- FRP dustbins in-place of metallic dustbins.
- Stuck Emergency windows
- Glass Windows not properly cleaned
- Electrical plug points and mobile charging points of varied designs/shapes
- Broken water bottle holders

These coaches were recently attended in major schedule (POH) in BVPW & GKPS workshops. Therefore, all POH workshops should be suitably advised to improve the standards of POH especially wrt to aesthetics and passenger amenities items of Rolling Stocks.

For necessary action please.

21/9/23

(रवि जैन)

कार्य.निदेशक / यांत्रिक इंजी. को.  
रेलवे बोर्ड

Copy to:

PCME/WR - For information and necessary action please.