

No. 2017/M(C)/138/2Pt1

(E-File No.-3325465)
New Delhi, Date:-12.07.2023

PCMEs

All Zonal Railways
& Konkan Railway


Sub: Investigation of issue related to sudden dropping and recreation of BP pressure in LHB rakes

- Ref: i. RDSO letter No. MC/LHB/Brake Dated 16.05.2023.
ii. Railway Board letter No. 2017/M(C)/138/2Pt1 Dated 13.12.2022.
iii. RDSO letter No. MC/LHB/Brake Dated 18.12.2022
iv. Railway Board letter No. 2022/M (N)/60/3 Dated 24.03.2022.

In reference to the issue related to sudden dropping and recreation of BP pressure in LHB rakes, RDSO has submitted a detailed investigation report vide letter under reference i above.

In this regard, all Zonal Railways are accordingly advised to take action to avoid such cases in future.

DA: As above.


(सुमन कुमार तांती)
निदेशक / यांत्रिक इंजी. को.
रेलवे बोर्ड

C/-PED/RS and ED/Carriage/RDSO for kind information and necessary action please.