



Government of India
Ministry of Railways
(Railway Board)

No. E(MPP)2016/3/8

New Delhi, dated 9.06.2016.

The General Managers,
All Indian Railways

Sub:-Derailment of Locomotive and 3 coaches of Train No. 14266 Dn Dehradum Varanasi Janata Express hauled by Locomotive No.11129 WDM3D/AMV at sand hump on loop line No.1 of Baccharawan station at Km. 1025/3-5 on Lucknow-Raibareli section of Lucknow Division of Northern Railway at 09.11 hours on 20.03.2015.

Commissioner of Railway Safety, South Central Circle's Final Report vide Para 9.4 on the above accident has recommended as under:

"Railway should avoid curtailing the periodical training of loco pilots which is essential for up-gradation and enhancement of their driving skill & safety knowledge."

This is brought to the notice of all Railways for information and necessary compliance.


(Anuradha Singh)
Director(MPP)
Railway Board