

I/3120616/2025

(भारतसरकार) GOVERNMENT OF INDIA
(रेलमंत्रालय) MINISTRY OF RAILWAYS
(रेलवेबोर्ड) RAILWAY BOARD

2020/Sig/31/Misc/24/Precautions (e-3319428) New Delhi, Dated 21.03.2025

The General Manager,
All Indian Railways,
Metro Railway, Kolkata

Sub: Summer & Monsoon Precautions for Signalling Systems.

During the Summer & Monsoon failures of signal, track circuits and points increase due to water leakage, water accumulation in the service buildings and in the points /track circuited area on account of surge and lightning strikes.

Based on feedback from Railways, Summer & Monsoon Precautions for Signalling System have been standardized and is being issued for uniform adoption over all Zonal Railways. Areas of concern should be identified and appropriate action to be taken to quantify, monitor and timely completion of all activities.

Zonal Railways are requested to kindly ensure that all instructions regarding Summer & Monsoon Precautions are communicated to all concerned down below and same are being implemented.

Encl: Annexure of Summer & Monsoon Precautions.

(Signature)
21/03/2025

रामेश्वरमीना

(Rameshwer Meena)

कार्यकारीनिदेशक(सिग्नल)

Executive Director (Sig)

E-mail: edsignal@rb.railnet.gov.in

Copy to: PCSTEs all Indian Railways & Metro Railway Kolkata.

I/3120616/2025

AnnexureSummer and Monsoon Precautions for Signalling Systems1. FIRE SAFETY:

- a. The availability of Fire extinguishers in prescribed size and numbers, removal of bushes/ waste from around porta cabins particularly for signalling equipments and DG sets, general clean up and removal of lube oil/ fuel oil from DG set enclosures, maintenance of standby DG sets and switchgear.
- b. Proper working of fire detection alarm system/fire suppression system should be ensured and inspected.
- c. Counseling of station masters regarding action to be taken in case of fire detection system alarms and awareness of other staff available at station to operate fire fighting equipments in case of exigencies.
- d. Conducting mock fire safety drills for sensitizing and training staff, ensuring they are well-prepared to handle emergency situations effectively.

2. TRACK CIRCUITS:

- a. Provision and cleaning of drainage system in yards to avoid water accumulation in points and track circuited area. Temporary drains need to be provided wherever required. Cross and longitudinal drains are to be made effective and are cleaned regularly during Monsoon and Rainy Season.
- b. Joint inspection of major yards prone to water logging by a team consisting of ADEN, ADSTE, AOM, ADEE and ADMO be carried out and action to be taken to improve the drainage before onset of monsoon. The concerned department shall take necessary action to ensure proper drainage.
- c. Joint inspection by SSE/P-Way & SSE/Sig to ensure:
 - i. Cleaning of ballast and ensuring at least 50 mm clearance of ballast from bottom of rail to avoid leakage of track circuit currents.
 - ii. Provision of 100% insulated GFN liners and rubber pads in track circuited areas with PSC sleepers.
 - iii. Replacement of worn out wooden sleepers, if any, and proper packing of ballast/ sleepers below insulated joints.
 - iv. Removal of vegetation, mud and muck from track circuited portion of the track as well as on either side of tracks and in vicinity.
 - v. All insulated nylon pieces of insulated joints, Insulation of stretcher bars & Point rodding are to be intact and replace those in bad condition.
 - vi. Defective /worn out glued joints are to be replaced before onset of monsoon.
 - vii. Provision of 'J' clips at all insulated joints on PSC sleepers.
- d. Track lead Junction Boxes in flood prone areas are raised without infringing SOD, so

I/3120616/2025

that water does not enter into them.

e. Adjustment of track circuit parameters to keep track relay pick up voltage within safe working limits.

f. Proper working of track feed charger failure alarm wherever provided.

g. Provision of self-restoring type PPTC fuses.

h. Track circuit /AFTC parameter adjustment is a dynamic process during rainy season i.e. it is not a onetime exercise. It is to be done with utmost care and should be done as per need and at-least just before start of monsoon and immediately after first shower.

i. Checking of all traction bonds in track circuited areas of track and attending deficiencies through Electrical Traction Department.

j. Checking and ensuring proper Earthing for axle counter field equipments & Evaluator.

k. Checking & ensuring of all connection like rods, transverse bonds, feeds of adjacent track circuits etc. do not touch the bottom of the rail. Proper condition of insulation sleeves on OHE bonds beneath rails to be ensured.

l. Timely replacement of old rusted track lead bond wires and defective Jumper cables.

3. POINTS:

a. Joint inspections of points & crossing with Engineering (P.Way) staff and immediate compliance of deficiencies noted during inspections.

b. Adjustment of point's rodding, adjustable crank and compensators for rod operated points and lock bar.

c. Testing of all emergency crossovers for their efficient working.

d. Insulation of point machines to be checked. All point motors carbon brush covers shall be sealed with silicon sealant after proper cleaning of commutators. Gear oil shall be filled in gear box and top cover sealed. Proper lacing and wiring, and greasing of the point machines should be completed. Crank handle contacts should be cleaned. Availability of Gasket and Carbon at point machine to be ensured.

e. At identified water logged and flood prone areas, use of IP67 point motors/ machines be preferably provided and water proofing/sealing of point machines as per CR practice, shall be done for the points identified in low lying areas.

f. Cable entries to be checked to ensure that the cable is in a healthy condition physically besides meggering and ELD monitoring. All the terminals to be cleaned to avoid deposition of moisture on the accumulated dust, to avoid low insulation.

g. Drills to be conducted for removal, replacing of point motors, detection contact assembly and clamping of points.

I/3120616/2025

h. Spare point motors and contact assemblies shall be kept at stations.

4. SIGNALS:

a. All signal units shall be examined to check the possibility of water seepage/ leakage inside the Signal Units. Signal units have to be sealed with proper gasket to prevent seepage of moisture /water. All signal unit lamps should be completely sealed including any holes to prevent moisture ingress.

b. CRUs of the LED Signal are to be applied with moisture super sealants coating, readily available in market to minimize their failures.

c. Additionally, a plastic cover wherever required shall be provided on the back of Signal units, in case, leakage /seepage persists. After the first showers, the signal units have to be re-examined and appropriate action to be taken to avoid water seepage/ leakage.

d. Any mechanical discrepancies/ damages in the signal units should be attended to ensure that the unit cover fits properly on the body and the locking arrangement is proper and watertight.

e. Strengthening of foundations of signal posts/location boxes should be done wherever required.

f. Availability of hood on CLS Signal units and Cleaning of LEDs of Signal units should be ensured.

5. RELAY ROOMS, CABINS AND EQUIPMENT ROOMS:

a. Based on history of previous years, joint inspection by sectional ADEN and ADSTE should be carried out to identify cabins/Relay room and equipment rooms prone to rain water leakage/ seepage and corrective steps be taken on a war footing.

b. Damaged/ broken windowpanes and doors etc. should be repaired to prevent water getting into relay rooms/cabins/equipment rooms, which may cause serious damage to the systems.

c. Ventilators should be cleaned. Aluminum stainless steel wire mesh be replaced wherever required. Broken glasses and structures should be repaired.

d. Visual inspection of relay wiring to ensure proper locking of connector clips.

e. Cleaning of relay room to make it dust free.

f. Roof over the relay room/battery room /panel room is cleaned to prevent accumulation of water on the roof. Drainpipes are available and cleaned.

g. Proper working of Air conditioners, wherever available should be ensured and power connections should be audited by Electrical (G).

h. Proper Working of exhaust fans in battery/IPS room should be ensured.

I/3120616/2025

6. POWER SUPPLY ARRANGEMENT:

- a. An audit of all the power supply equipments' rating including electrical cables and joints, MCBs, Switches, Changeovers, etc should be meticulously conducted. Additionally, visual/physical inspections must be carried out to ensure these components are neither burnt nor overheating. Thermal Scanners may also be used for this purpose.
- b. Working of all stand-by Power Supply arrangements shall be ensured.
- c. Working of Autochange-overs for Power supplies at Stations, End Goomties, IBS & Auto sections have to be checked and ensured.
- d. To ensure the availability of power supply to Signalling System, Diesel Generators wherever provided be checked and should be made functional and kept in good fettle. Adequate quantity of Diesel, Mobil Oil, etc. should be stocked at the stations provided with DG sets.
- e. Load testing of batteries should be carried out. Secondary cells working beyond codal life/Defective secondary cells have to be identified and replaced on priority.
- f. All battery terminals are to be inspected regularly to be free from sulphation. Also, Proper functioning of distilled water plants, if available, to be ensured.
- g. All IPSs must be checked at SE/SSE's level for running the IPS on backup battery, checking the auto change over functions, the functioning of the DC-DC converters, the status of the CVT and inverters, class-B protection against power surge etc. Earthing and all relevant values checked, rectified and to be recorded by SE/SSE concerned.
- h. Availability and intactness of Class-B & C Surge Protection devices which are wired in a separate wall mountable box shall be checked for their indications, if available.
- i. Earth leakage on existing power supplies should be removed by isolating the faults and replacing the conductors. ELD indications shall be linked with data logger and data obtained should be studied to isolate and remove the faults quickly.
- j. Monitoring of battery chargers through RTU/ SMs to be provided at stations where no S&T staffs is available (IBS).
- k. Ensure the provision of spare battery chargers of different capacity at strategic locations.

7. S&T CABLES:

- a. Testing of main, tail and power cables should be completed and low insulation conductors to be transferred on healthy conductor in time.
- b. Earth Leakage Detectors, where provided, have to be tested for their working for monitoring for any low insulation of conductors. ELD data to be linked with Data Loggers for effective monitoring.
- c. All defective tail cables to be replaced before monsoon. All tail cables at entry of Junction boxes, Location boxes, Signal posts are checked for breakage of insulation. All the

I/3120616/2025

earth faults should be removed.

- d. Minimum 5% healthy spare conductors are to be made available in each location / Goomty / relay room. These identified spare conductors have to be kept labeled /marked so that restoration time for attending signal failure on account of defective cables can be minimized.
- e. All spare conductors must be tested. Spare cable details shall also be recorded in cable core plan and insulation measurement register.
- f. All the Supervisors shall familiarize themselves with the position of spare conductors in their respective sections. JPO should be strictly followed while doing earth work in the station yards.
- g. Protective works provided for the cables at places like track crossings, culverts, bridges, etc shall be inspected prior to onset of monsoon and special attention has to paid to these protective works soon after the first shower.
- h. Drills have to be conducted for all Maintainers and Supervisors in the Section for transferring functions to spare conductors in case working conductors become defective.
- i. Proper earthing of the armour of all cables and continuity of cable armour to be ensured.
- j. Spare S&T cables of various core sizes are kept at identified stations. One dedicated signalling cable from relay room to either side shall be kept tested and tagged for easy identification for use in emergency.
- k. Quad cable meant for Block should be tested for their insulation resistance, cross talk, loop resistance and db losses. Parameters should be brought within acceptable limits. Position of cable joints should be known accurately and joints repaired if required before onset of rains.
- l. Gain of OFC channels used for BPAC/ UFSBI should be adjusted within permissible limits.
- m. At locations where HT cables are crossing the track, it may be ensured that special precautions are in place to prevent any accidental leakage of current from these should not damage S&T cables.

8. LOCATION BOXES:

- a. It should be ensured that doors of all location boxes are closed properly and there are no extra vents, which may allow entry of water or insects/rodents inside the location boxes.
- b. Damaged/ corroded portions of location boxes should be repaired / replaced. There should not be any space between the base of the location box and its foundation. Any such space, if existing, should be filled up by mortar.
- c. Location boxes on the banks should be kept vertical by providing strong foundation. Location boxes which are likely to tilt should be attended so as to prevent tilting. Suitable measures shall be taken to prevent ingress of water in location boxes and junction boxes.

I/3120616/2025

- d. Any location box lying in low level and likely to flooded should be raised/shifted and protected appropriately.
- e. Suitable measures to be taken to prevent ingress of water in location boxes and junction boxes by application of gasket/monopolist/M-seal/tapes etc.
- f. All the terminals in the location boxes and junction boxes are to be cleaned to avoid low insulation due to moisture deposition on the accumulated dust.
- g. PPTC fuses of specific capacity to be provided for all external fuses in location boxes etc.
- h. Telephones in location boxes, if provided, to be tested for proper functioning.

9. EARTHING & LIGHTNING PROTECTION DEVICES:

- a. Proper Earthing and Lightning Protections are provided as per extant instructions on all the equipments like Block Instruments, IPS, Axle Counters (UAC/DAC/MSDAC), EI etc. It should be ensured that all these devices are in proper working order. Defective devices should be identified and replaced.
- b. Earth resistance value of all earthing arrangement should be measured and ensured that it is within permissible limits by adopting necessary measures. Provision of additional Earths or overhauling of Earths may be undertaken wherever warranted.
- c. Earth connection at the Earth bar/location body/equipment side and at the Earthing rod/pipe must be thoroughly cleaned to provide proper connectivity. Rusted bond wires/cables used for Earthing should be replaced.
- d. Provision of 'A' class protection at service building housing EI/IPS/MSDAC and other electronic equipments.
- e. Provision and intactness of Earth resistance of lightening protection devices at each identified place such as IPS, EI, AFTC, Axle Counters etc.

10. OPERATING CUM INDICATION PANEL/VDU:

- a. 40/60 conductor indoor cable between panel and relay room shall be checked for proper working. Sufficient spare cores shall be ensured.
- b. OFC for VDUs shall be checked for proper working and sufficient backup of Inverters provided for VDUs shall be ensured.
- c. ASMs room shall be attended to prevent water falling on the Operating – Cum Indication panel.
- d. Working of 'Calling On' signals have to be ensured.
- e. Joint Drill has to be conducted with Operating for Emergency operation of Point through Panel, extraction of Emergency Crank Handles and cranking of point machines.
- f. Testing of farthest points & crossings and emergency crossovers to be done for proper

I/3120616/2025

working.

g. All Panel Indications shall be checked and defective bulbs or LEDs have to be replaced. Similarly, indications in case of dual VDUs shall be ensured.

h. Spare items viz., all type of Panel buttons, ECRs, Relays, Timers, Condensers, Resistors, Fuses, track feed chargers have to be made available at each station during monsoon. One pair of spare Transmitter and Receiver of each frequency shall be made available for section where Daido types TLBIs exist.

11. LEVEL CROSSING GATE:

- a. Defective wire insulators, rusted wire ropes and rod insulator are to be replaced.
- b. Pipes through which rods or wires run should be cleared regularly.
- c. Gate telephones shall be tested and telephone battery shall be replaced if required.
- d. Area on either side of road & across the gate tracks to be specifically inspected to ensure that no water is getting accumulated.
- e. Sliding booms, wherever provided, shall be kept in working order.
- f. Sufficient spares of ELB (Boom, Belt, limit switch, fuses) should be kept ready.
- g. It should be checked jointly with Electrical Traction branch that there is no possibility of boom getting entangle with OHE in case of storm /high pressure winds.

12. ELECTRONIC INTERLOCKING:

- a. Earthing arrangement as well as Surge and Lightning Protection measures should be checked and to be available as stipulated.
- b. Both Main as well as Standby systems, DC-DC converters, CCIPP and VDU or both the VDUs (as the case may be) should be tested to be in working order. Record of testing should be maintained in a register.
- c. Spare cards of EI and spare DC-DC converters etc. Should be kept at all critical locations.
- d. In areas highly vulnerable to lightning, safeguards as per local Railway's practice as decided by PCSTE of the Railway be kept in place to ensure trouble free working of EI during Monsoon.
- e. Back up panel/Fall Back panel should be kept ready for restoring the degraded working.
- f. Requisite precautions shall be taken for EI as per OEM's instructions and RDSO guidelines. Addresses and Mobile /Land Line Telephone numbers of all concerned S&T staff/officers and OEM Supervisors shall be kept with in-charge Signal Supervisors and Signal Fault Controller/Test Room.

I/3120616/2025

13 GENERAL:

- a. Sensitive Signalling Equipment like TPWS, SSDAC, MSDAC, EI, IPS, Data Logger, UFSBI, AFTC etc shall be got checked and audited with OEMs and maintenance check list of the equipment shall be complied with.
- b. All spare cards of TPWS, EIs, AFTCs and Digital Axle Counters etc. should be checked by putting them in working circuits and thereafter properly stacked.
- c. Emergency lights, torches and petromax should be checked and kept in readiness with adequate quantity of torch cells/ kerosene oil, etc.
- d. All the measuring instruments like cable testers, cable route locators, Insulation tester, earth resistance Tester, and Multimeters available with Technician/JE/SSE must be checked for their proper functioning.
- e. Transport facilities (with vehicle and driver) should be made available round the clock at critical locations during monsoon to move the staff at the earliest during emergency.
- f. Night failure gangs may be formed by pooling resources and stationed at critical locations for attending defects of Signalling system due to heavy rain, etc. in shortest possible time. Their contact nos. shall be displayed in BOLD in Test Rooms.
- g. On Suburban sections where AWS is provided, all AWS track magnets along with Opto-Coupler covers shall be sealed with silicon sealant and covered with plastic sheet. At TPWS/ ETCS/TCAS locations Balises/ RFIDs are also protected against any entry of moisture.
- h. All the terminals in location and junction boxes should be cleaned to avoid low insulation due to moisture deposition on the accumulated dust.
- i. Usage of Ant-Powder, Rat-cake etc. to be explored in vulnerable boxes /cabins/ rooms/ signals etc. where such issues have been experienced in the past.
- j. Regular watch to be made in the vulnerable areas like Bridges, Ponds etc where Signalling equipments are likely to be affected.
- k. Provision of pumping sets of sufficient capacity to be done at vulnerable locations of water logging at identified locations where water logging was noticed during previous monsoon.
- l. After inspections, compliance from each sectional JE/SSE shall be obtained by the officer in charge. Sr. DSTEs shall send consolidated compliance of the Divisions to Head Quarter. Sr. DSTEs of Divisions, CSE and other Headquarters officers shall conduct surprise checks to confirm compliance of above instructions.

14. MONSOON DRILL:

- a. Drills to be conducted for all ESMs, JEs & SSEs in removal, replacing of point motors, detection assembly and clamping of points during flooding of tracks and it is to be recommended in register.
- b. Drills to be conducted for all ESMs, JEs & SSEs in case working conductors become defective and it is to be recommended in register.
