

9. P

भारत सरकार/GOVERNMENT OF INDIA
रेल मंत्रालय/MINISTRY OF RAILWAYS
रेलवे बोर्ड/(RAILWAY BOARD)

No. 2018/Sig/1/Sig Equip/IPS/1

New Delhi, Dtd. 12th January, 2018


PCSTE
West Central Railway

Sub: - Siemens Electronic Interlocking - Provision of newer version power supply Card PSU 24.

Ref:- WCR's letter No. WCR/N-HQ/110/SSI-Corres/Sig-70 PtIV dtd. 02.01.2018.

Considering several "C-Zero" errors in EI systems installed at WC Railway, RDSO has suggested WC Railway to replace power supply cards by newer version i.e. PSU 24 vide Jt. Director/Sig-III/RDSO's letter No. STS/L/SSI/CA/IRSI/Vol-33 dtd. 22.03.2017. It has been noticed that newer version Power supply card i.e. PSU 24 has been provided selectively either in 'A' or 'B' system or both at some stations. It should have been replaced in both working and Standby systems of a station.

This new Power Supply card (PSU 24) are required to be provided in all EIs of M/s. Siemens/Westrace make to eliminate possible cause of "C-Zero" error. It is requested to kindly have a joint meeting with M/s. Siemens and RDSO and chalk out programme for providing PSU 24 Cards in a time bound manner.


12/01/18
(Arjun Singh Tomar)
Director (Signal), Railway Board

Copy to:-

- i) ED/Sig (Coord)/RDSO
- ii) PCSTEs/All Indian Railways for similar action.