

## भारत सरकार Government of India रेल मंत्रालय Ministry of Railways रेलवे बोर्ड Railway Board



(E- File No. 3350906)

2021/M(C)/142/4 (5)

New Delhi, Dated - 22.04.22

The Principal Chief Mechanical Engineers, All Zonal Railways.

Sub: Distribution of RSP work of Modification in Air Brake pipe line and associated fittings for 5,000 coaches (P.B. Item No. 1269/22-23).

Ref: (i) Railway Board letter No. 2021/M(C)/142/4 (5) Dated 02.06.21.

(ii) ED(Stds)/Carriage/RDSO's letter No. No.MC/LHB/Brake Dated 24.06.19.

RSP work of Modification in the air brake pipeline & associated fittings for 5,000 coaches sanctioned under Pink Book Item No.712/22-23 (1313/21-22) was distributed among Zonal Railways vide letter under reference (i) above. However, the work has been completed in only 1058 coaches. The ZR wise progress has been as below:-

| ZRs  | Allotment | Execution | Balance still not | ZRs  | Allotment | Execution | Balance still |
|------|-----------|-----------|-------------------|------|-----------|-----------|---------------|
|      |           |           | executed          |      |           |           | not executed  |
| CR   | 300       | 0         | 300               | SR   | 460       | 0         | 460           |
| ECR  | 541       | 0         | 541               | SECR | 324       | 0         | 324           |
| ECoR | 200       | 0         | 200               | SWR  | 800       | 0         | 800           |
| NR   | 200       | 200       | 0                 | WR   | 1000      | 466       | 534           |
| NER  | 600       | 87        | 513               | WCR  | 575       | 305       | 270           |

Another RSP work of Modification in Air Brake pipe line and associated fittings for 5,000 coaches has been sanctioned under P.B. Item No. 1269/22-23. Based on requirement received from ZRs, the subject RSP work is distributed among ZRs as per the following distribution:-

| Zonal Railway | Distribution (coaches) | Zonal Railway | Distribution (coaches) |  |  |
|---------------|------------------------|---------------|------------------------|--|--|
| CR            | 270                    | NWR           | 70                     |  |  |
| ER            | 791                    | SR            | 0                      |  |  |
| ECR           | 44                     | SCR           | 0                      |  |  |
| ECoR          | 200                    | SER           | 550<br>0<br>0          |  |  |
| NR            | 871                    | SECR          |                        |  |  |
| NCR           | 114                    | SWR           |                        |  |  |
| NER           | 970                    | WR            | 220                    |  |  |
| NFR           | 900                    | WCR           | 0                      |  |  |
|               | Total                  | 5000          |                        |  |  |

Zonal Railways are advised to expedite the retrofitment work in LHB coaches as per RDSO instructions under reference (ii) above or latest and target completion of both the RSP works in 22-23.

Zonal Railways are advised to accordingly indicate fund requirement against the RSP work at appropriate budgetary stages (RE, FM).

निदेशक / यांत्रिक इंजी. को.

रेलवे बोर्ड

Copy to: ED/Carriage/RDSO - For kind information and necessary action please.