भारत सरकार Government of India रेल मंत्रालय Ministry of Railways रेलवे बोर्ड Railway Board

No.2023/M(C)/141/6

New Delhi, dt.30.09.2024

Principal Chief Mechanical Engineers, All Zonal Railways.

Sub: Locking arrangement for isolating cock of FSDS & sealing of solenoid valve of FDSS.

Ref: i. RDSO letter no. MC/ACF/Fire Supprn/PC dated 06.06.2024.

ii.RCF Coach Alteration Instruction no. CAI/RCF/MECH/LHB/064 dated 22.05.2024.

Vide reference (i) above, RDSO has issued the instructions for locking arrangement for isolating cock of FSDS of AC coaches & sealing of solenoid valve of FDSS of pantry/power cars. Progress of implementation of above said instructions have been reviewed at Board. It has been observed that all coaches are yet to be tackled for the same.

Accordingly, It is advised that locking arrangement of isolating cock of FSDS and sealing of solenoid valve of FDSS to be completed for all eligible coaches by 10.10.2024.

Also, the work of upgradation of manual FDSS of pantry/power cars into automatic FDSS of pantry/power cars be done on priority.

Action taken report be sent to Board on (somech538@gmail.com).

(ऐश्वर्य सचान) संयुक्त निदेशक / यांत्रिक इंजी. कोचिंग

Copy to: PED/RS/RDSO- for kind information please.

Sr. No. Railways hc Railways 1 CR 2 ECOR 3 ECR 4 ER 5 NCR 6 NER 7 NFR				
	No. of coaches in holding with FSDS systems	No. of power cars/pantry cars in holding with FDSS systems	datewith APD for Isolation valve as per RDSO L. No. MD46111	No. of coaches on date with sealed Solenoid Valve as per RDSO L. No. MC/ACF/Fire Supprn/PC dated 06.06.2024
	1499	226	908	123
	1127	191	49	101
	1275	217	55	190
+	1313	246	128	18
+	299	59	18	2 ~
7 NFR	1270	130	821	107
	1162	227	125	57
8 NR	2108	326	52	325
9 NWR	1074	165	894	140
10 SCR	1383	184	44	65
	415	50	30	20
-	1270	200	342	36
+	1683	221	384	33
+	686	203	368	56
	618	50	20	13
	2119	347	167	156
17 KR	34	12	0	12
Total	20006	3054	4402	1453