

G11F.

भारत सरकार GOVERNMENT OF INDIA
रेल मंत्रालय MINISTRY OF RAILWAYS
(रेलवे बोर्ड RAILWAY BOARD)

No. 2017/M(C)/141/2 Pt

New Delhi, Dated: 12.09.2019

The Principal Chief Mechanical Engineers,
All Indian Railways

ED/carriage
RDSO/LKO

Sub: Display OF national flag on the exterior wall of coaches.
Ref: 1. This Office letter of even No. Dated 06.08.2018.
2. This Office letter of even No. Dated 03.07.2018.

Vide letter at Ref.1 Zonal Railways were advised to display the sticker of Swacchata logo and National Flag at the entrance doors of coaches on the exterior wall as per annexure as drawing no CG-18207 with the letter.


Further, Vide letter under reference 2, Zonal Railways were advised to use the Swachchhta logo approved by Ministry of Culture in place of Swacchata logo specified vide letter under reference 1.

Further in above reference RDSO is advised to modify the Drawing No CG-18207 by removing the prescribed 5 mm thick black boundary as per provisions of the Flag Code of India 2002 and according^{ly} advisory issued by Ministry of Home affairs vide File No 15/01/2019-Public Dated 01.08.2019 and incorporating the swachchhta logo as advised vide reference under 2 above.

Furthermore, Zonal Railways are also advised to provide display of National Flag without boundary as mentioned above. Remaining other stipulations specific to Indian Railway coaches will remain same.

For immediate and strict compliance please.

This is being issued with the approval of the competent authority.


(Suman Kumar Tanti)
Dir. Mech. Engg. (Chg.)
Railway Board