



भारत सरकार Government of India
रेल मंत्रालय Ministry of Railways
रेलवे बोर्ड Railway Board



No. 2020/M(C)/137/11

(E-File no. 3326753)
New Delhi, Dated-05.04.2022

General Manager,
MCF, Rae Bareli

Sub: Insufficient space to keep linen in Tejas sleeper and other Coaches.
Ref: WR's letter no. M-274/10 dated 25.03.2022.

Vide letter under reference, PCME/WR has raised concern related to insufficient space for linen storage in TEJAS sleeper Coaches, which has been compromised while manufacturing, to accommodate control panels of various additional equipments like automatic doors, CCTV, Fire detection cum alarm systems etc.

With the restoration of provision of Linen in trains, Zonal Railways are facing problems in linen storage. This problem is especially severe in Tejas sleeper coaches manufactured by MCF.

The matter has been viewed very seriously and accordingly the following actions may be taken immediately

1. These coaches are modified over Zonal Railways to restore the designated linen space available.
2. Detailed report to be sent to Board along with fixing the responsibility for the same

It is further advised to complete the above work by 30th April 2022.

The matter may please be treated as **most Urgent**.

(सुमन कुमार तौती)

निदेशक / यांत्रिक इजी. कोचिंग

रेलवे बोर्ड

C/o- PPS to MTRS/RB for kind information of MTRS/RB please.

-AM/PU/RB for kind information and necessary action please.

-All PCMEs/ Zonal Railways and ICF, RCF & MCF for kind information and necessary action please.