

भारत सरकार / GOVERNMENT OF INDIA  
रेल मंत्रालय / MINISTRY OF RAILWAYS  
(रेलवे बोर्ड / RAILWAY BOARD)

No.2008/M(W)/814/10

New Delhi, dated 27.05.08

The Chief Mechanical Engineers  
Central Railway, Mumbai.  
East Coast Railway, Mancheswar  
N.F. Railway, Guwahati.

Southern Railway, Chennai.  
S.C. Railway, Secunderabad.  
Western Railway, Mumbai.

Sub: Painting of coaches during POH in workshops.

Recently, a Quality Audit had been conducted by RDSO (M&C Dte.) in various workshops over Indian Railways regarding the quality of exterior painting procedure being followed. One of the salient points being observed in almost all the workshops covered was that very few coaches were given 'A' schedule painting in the workshop. It appears that the 'A' schedule attention of coaches is not being followed as per the schedules prescribed in the Maintenance Manual.

The condition and quality of painting has already been causing adverse comments on no. of occasions. The matter may please be looked into and it be ensured that 'A' schedule painting attention is given to coaches as per the prescribed procedure. Action taken in this regard may please be advised.

*Ajay Nandan*  
(Ajay Nandan)  
Dir.Mech.Engg.(P)I  
Railway Board.

o/c

*अजय नन्दन*

*27/5/08*

*R*  
*30/5*