

S.No 27

**GOVERNMENT OF INDIA
MINISTRY OF RAILWAYS
(RAILWAY BOARD)**

No.2012/Proj./Jaipur/30/7Vol.II

New Delhi, date 22.04.2014

Chairman & Managing Director,
Jaipur Metro Rail Corporation Ltd.,
Khanij Bhawan,
Udyog Bhawan Premises,
Tilak Marg, C- Scheme,
Jaipur-302005.

Sub: Approval of Annexure C-1 for Phase- 1 of Jaipur Metro.

Ref: (i) JMRCL's Letter No. F7(B-39) JMRC/RDSO/C1/2013/1686 dated 14.03.2014.
(ii) JMRCL's Letter No. F7(B-39) JMRC/RDSO/C1/2013/1840 dated 28.03.2014. S.No 23
(iii) DMRC's Letter No. DMRC/CGM/Track/Misc./2013 dated 15.04.2014. S.No 25
(iv) Board's Letter No. 2012/Proj./Jaipur/30/7Vol.II dated 20.12.2013. S.No 13

Jaipur Metro Rail Corporation Ltd.'s request for dispensing the conditions in Para 2 (i) and (ii) referred to in Board's Letter of even number dated 20.12.2013 has been examined at Board's level and considering the overall safety aspects, it has been decided that while the stipulation made in Para 2(i) of Board's aforesaid letter dated 20.12.2013 shall remain the same, the condition laid down in Para 2 (ii) is dispensed with keeping in view the observations made as under:-

- (i) All flash butt welds are found to be satisfactory in all tests mentioned in RDSO Manual for Flash Butt Weld of Rail and USFD testing.
- (ii) Signaling system provides additional safeguard. However, any in-service failure of such weld shall be reported to RDSO, without any delay, for their appraisal.

It is presumed that future welding will be without any short comings and will not require joggling in any case.

o/c
Ruth Changsan
22-04-14
(Ruth Changsan)
Director/Works Planning
Railway Board
Tel. 23097061

Copy to /-

1. Executive Director/UTHS, RDSO, Manak Nagar, Lucknow.
 2. Executive Director/Track-I & Executive Director/Track-II RDSO, Lucknow.
 3. DMRC w.r.t. their letter dated 15.04.2014.
- 63M*