

G.f.

GOVERNMENT OF INDIA (भारत सरकार)
MINISTRY OF RAILWAYS (रेल मंत्रालय)
RAILWAY BOARD (रेलवेबोर्ड)

No.2018/Sig/18/6-Data Logger/1

New Delhi, dated 16th October, 2018

The General Managers
All Zonal Railways, CORE & Metro/Kolkata


Sub: Monitoring of Relay Room Door Closure through Data Logger.

Ref: - RDSO's Letter No. STS/E/Data logger/Vol.XXdtd.12.09.2011.

Detailed guidelines were issued by RDSO for monitoring of Signaling system through data logger. This also includes monitoring of Relay Room Door Closure/Opening through Data logger by generation of SMS alert. It is understood that the door of all the relay rooms on your Railway have been provided with door Closing /Opening monitoring system.

As desired by CRB, It may kindly be ensured that all the Relay Rooms door opening/closure is being monitored through data loggers. Any discrepancy noticed should be attended promptly and rectified within 24 hrs.

Sectional Supervisor shall be held responsible in the event of door Closure/Opening monitoring system is found non-functional for more than 24 hours.


16/10/18
(Arjun Singh Tomar)
निदेशक (सिगनल)

Copy to: - For necessary action please.

- i) PCSTEs/All Indian Railways & Metro/Kolkata
- ii) CSTE/CORE, Allahabad
- iii) Director/IRISET, Secunderabad
- iv) ED (Sig)/Co-ord/RDSO, Lucknow