

GOVERNMENT OF INDIA (भारत सरकार)
MINISTRY OF RAILWAYS (रेल मंत्रालय)
(RAILWAY BOARD) (रेलवे बोर्ड)

No.2019/Track-III/TK/13


New Delhi, dated 14.11.2024.

Principal Executive Director/Infra-I
RDSO
Manak Nagar,
Lucknow.

Sub: Provision of Proximity Sensors in the track machines to prevent dashing of machine.

There were few incidences of dashing of Track machine with other track machines/ rolling stock in the past. This was also discussed during the safety review meeting held on 11.11.2024. It is understood that if Proximity Sensors are provided in the machine on both ends, then it may be helpful in preventing dashing of the machines with other rolling stock.

RDSO is advised to study the issue and submit their report about the possibility of fixing such proximity sensors and their control systems.


14/11/2024

(Vijay Singh)
Executive Director Track (M & MC)
Railway Board
Tele: No. 011- 47845531
Email_ID : vijay.singh.2017@gov.in
Room No. 150, First Floor, Rail Bhawan
Raisina Road, New Delhi - 110 001.